


# BACKGROUND Stormwater

3

# Background Review – Stormwater



- Development constraints associated with the tributaries, including the TRCA regulation limits.
- The north parcel top of bank has been staked and resulted in a refinement of the floodlines
- Observations of flooding along Highway 7 towards the western limit of study area

